

VOLVO - INSPECTION REPORT

Volvo, A40G - Articulated haul trucks

Country: US
Date: 09/17/2019
Make: Volvo
Serial number: 341091
Trans S/N: 1700106451

Dealer: Alta Equipment Company
Inspector: Anthony M
Model: A40G
Engine S/N: 092266

Location: New Hudson
Year: 2016
Hours: 5220
Matris hours: 5226

Comment:

Equipped Configuration

<input checked="" type="checkbox"/> Yes Standard Cab	<input type="checkbox"/> Yes Scraper ARR.G.	<input type="checkbox"/> Yes Fuel Heater
<input type="checkbox"/> Yes Water Tank	<input type="checkbox"/> Yes Low Profile Cab	<input type="checkbox"/> Yes Full Suspension
<input type="checkbox"/> Yes LED Light	<input checked="" type="checkbox"/> Yes Standard Body	<input type="checkbox"/> Yes Frame Ext.
<input checked="" type="checkbox"/> Yes Strobe Light	<input type="checkbox"/> Yes Extra Spill Guard	<input checked="" type="checkbox"/> Yes Onboard Weight Sys.
<input type="checkbox"/> Yes Hydraulic switch control	<input type="checkbox"/> Yes Exhaust Body Heat	<input type="checkbox"/> Yes Bed Liner Metal
<input checked="" type="checkbox"/> Yes Hydraulic lever control	<input checked="" type="checkbox"/> Yes Overhung Tailgate	<input type="checkbox"/> Yes Bed Liner Plastic
<input type="checkbox"/> Yes Auto Lube System	<input type="checkbox"/> Yes Underhung Tailgate	<input checked="" type="checkbox"/> Yes Back Up Camera
<input type="checkbox"/> Yes Fire Suppression System	<input type="checkbox"/> Yes Underground ARR.G.	<input type="checkbox"/> Yes Fast Fuel
<input checked="" type="checkbox"/> Yes Mud Flaps		

Comment:

Images

Comment:

Operators Station

Seats and armrest Fair Remarks:

Dash and console Fair Remarks:

Floor Board/Mat Good

Cab glass Good

Mirrors Good

Interior light Good

Switches Good

Wipers Good

Gauges Good

Hydraulic controls Good

Powertrain controls Good

AC cooling Good

CAB Interior Good

Operators station
condition summary

Comment:

Outside appearance

Steps	[X] Fair	Remarks: <input type="text" value="cab entry steps bent but works"/>
Hand rails	[X] Good	
Counterweight /	[X] Good	
Bumper		
Grill	[X] Good	
Hood	[X] Good	
Exhaust stack	[X] Good	
Pre-cleaner bowl	[X] Good	
Front fenders	[X] Good	
Hyd tank	[X] Good	
Fuel tank	[X] Good	
Def tank	[X] Good	
Front frame & welds	[X] Good	
Rear frame & welds	[X] Good	
Sheet metal	[X] Good	
Paint	[X] Good	
Outside appearance condition summary	<input type="text"/>	
Comment:	<input type="text"/>	

Safety condition

Safety decals in place	[X] Yes	
Operators manual	[X] Yes	
Safety handles	[X] Good	
Seat belt	[X] Good	
Horn	[X] Good	
Back up alarm	[X] Good	
Brake lights	[X] Good	
Turn signals	[X] Good	
Hazard lights	[X] Good	
ROPS Structure	[X] Good	
CAB	[X] Good	
Safety condition summary	<input type="text"/>	
Comment:	<input type="text"/>	

Electrical condition

Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good

Wiring harness's [X] Good
Key switch [X] Good
Switches [X] Good
Lighting [X] Good
Engine preheater [X] Good
Batteries / Connections [X] Good
Battery disconnect [X] Good

switch

Electrical condition
summary

Comment:

Engine condition

Oil level OK [X] Yes
Water in oil [X] No
Compression in radiator [X] No
Blow by [X] No
Engine knocking [X] No
CE PLATE [X] No
Oil pressure [X] Good
Oil leaks [X] No
EPA DECAL [X] Yes
Turbo charger [X] Good
Exhaust manifold [X] Good
Muffler [X] Good
Fuel injection system [X] Good
Head gasket [X] Good
Head [X] Good
Fan guard [X] Good
Belts & pulleys [X] Good
Wiring harness [X] Good
Starter [X] Good
Alternator [X] Good
Seals & gaskets [X] Good
Engine mounts [X] Good
Brackets [X] Good
AC Compressor [X] Good

Air filters [X] Good

Engine condition
summary

Comment:

Cooling system

Coolant color

Radiator [X] Good

Water pump [X] Good

Oil cooler [X] Good

Fan [X] Good

Fan drive [X] Good

Hoses [X] Good

Cooling system
summary

Comment:

Transmission condition

Oil level OK [X] Yes

Water in oil [X] Yes

Any leaks [X] Yes

Torque converter [X] Good

Case [X] Good

Pump [X] Good

Hoses [X] Good

Retarder [X] Good

Transfer case [X] Good

Shifting forward [X] Good

Shifting reverse [X] Good

Transmission summary

Comment:

Axels-Final Drives-Brakes

Front differential [X] Good

Center differential [X] Good

Rear differential [X] Good

Differential supports [X] Good
Drive shafts [X] Good
UV Joints [X] Good
Planetaires front [X] Good
Planetaires center [X] Good
Planetaires rear [X] Good
Hoses / Lines [X] Good
Torsion rods [X] Good
Holds in park [X] Yes
Brakes wet [X] Yes
Holds thru all gears [X] Yes
Brakes dry [X] No
Brake disk / calipers [X] Good
Brake lines [X] Good
Seals [X] Good
Parking brake [X] Good

Summary

Comment:

Steering & articulation condition

Steering cylinders [X] Good
Pumps [X] Good
Valves [X] Good
Lines / Hoses [X] Good
Secondary steering [X] Good
Steering pins & bushings [X] Good
Steering wheel tilt & function [X] Good
Articulation pins & bushings [X] Good

Summary

Comment:

Hydraulics condition

Bed lift cylinders [X] Good
Pumps [X] Good
Valves [X] Good
Hoses [X] Good
Fittings [X] Good
Tank [X] Good

Controls [X] Good
Bed float [X] Good
Operational condition [X] Good

Summary

Comment:

Bed & other attachments

Bed type / Size

Tailgate S / N

Bed serial

Addtl attachments

Spill guard [X] Good

Body [X] Good

Bed liner [X] Good

Bed sides [X] Good

Bed floor [X] Good

Wear plates [X] Good

Tailgate [X] Good

Pins & bushings [X] Good

Summary

Comment:

Tires & rims

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Make

Serial

% Remaining

Recapped No

Tread cuts No

Side wall cuts No

Tire size the same Yes Remarks:

Overall tire condition Good

Rims Good

Lug nuts & studs Good

Comment:



General Comments

Legend (5 star rating) 4

Paint general Good

Comment: