

Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H

UNIT # 631127
Location: ASC, Greenville NC



SPECIFICATIONS

VIN	631127
LeaseInspector ID #	631127
Year	2016
Model	Volvo L110H
Location City	Greenville
Location State	NC
General Specifications	
New Hours	3298
Old Hours	3295

Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H

UNIT # 631127
Location: ASC, Greenville NC

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H

UNIT # 631127
Location: ASC, Greenville NC

DEFICIENCY REVIEW

ITEM

1. Bucket Sides Rusted, Edges Bent-
Repaired
2. Excessive Rust/Corrosion- Repaired
3. Repair Windshield Chips- Replaced
4. Oil Leak at Front Axle- Repaired

QTY PRICE


\$0.00
\$0.00
\$0.00
\$0.00
\$0.00

Total

Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H



UNIT # 631127
Location: ASC, Greenville NC



Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H



UNIT # 631127
Location: ASC, Greenville NC



Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H

UNIT # 631127
Location: ASC, Greenville NC



Lessee: Advanced Residuals
Contract: 502-7525689-035

Unit: 2016 Volvo L110H

UNIT # 631127
Location: ASC, Greenville NC

