Lessee: Superior Construction Company Contract: 502-7674819-024

Unit: 2016 Volvo L110H

UNIT # 631050 Location: Flagler Construction, Jacksonville FL



SPECIFICATIONS

531050
531050
2016
/olvo L110H
lacksonville
=L
1450
1446

Lessee: Superior Construction Company Contract: 502-7674819-024 Unit: 2016 Volvo L110H

UNIT # 631050 Location: Flagler Construction, Jacksonville FL

ADDITIONAL FEATURES OF THIS VEHICLE

COMMENTS

Appraiser Comments:

Creditor Comments:

Public Comments:


Starts/Runs: Yes Overall: Fair

Lessee: Superior Construction Company Contract: 502-7674819-024	Unit: 2016 Volvo L110H	UNIT # 631050 Location: Flagler Construction, Jacksonville FL
	DEFICIENCY REVIEW	
ITEM	QTY PRICE	
1. Can Door Lock Cylinder Damaged- Replaced	\$0.00	
2. Dealer to Determine is Service is Due- Up to Date	\$0.00	
3. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00	
4. Coolant Level Low- Repaired	\$0.00	
5. Bucket Cylinder Collection - Repaired	\$0.00	
6. Cutting Edge Worn, Not Turned- Unable to Locate Bucket	\$0.00	
7. Counterweight Pin Missing- Replaced	\$0.00	
8. 3 Damaged Mudflaps- 4 Replaced	\$0.00	
9. Right Rear Mudflap Hanger Bent- Repaired	\$0.00	
10. Seat Belt Does Not Retract- Replaced	\$0.00	
11. Windshield Wipers Damaged- Replaced	\$0.00	
12. Radiatr Grille Dented, Frame Damaged- Grille Not Repaired, Frame Repair Attempted	\$0.00	
13. Left Rear Step Missing- Not Replaced	\$0.00	
Total	\$0.00	



Unit: 2016 Volvo L110H

UNIT # 631050 Location: Flagler Construction, Jacksonville FL






UNIT # 631050 Location: Flagler Construction, Jacksonville FL



Unit: 2016 Volvo L110H



Lessee: Superior Construction Company Contract: 502-7674819-024

Unit: 2016 Volvo L110H

UNIT # 631050 Location: Flagler Construction, Jacksonville FL

