

Lessee: Trader Construction Co
Contract: 502-7522971-059

Unit: 2017 Volvo A40G

UNIT # 341672
Location: ASC, Greenville NC



SPECIFICATIONS

VIN	341672
LeaseInspector ID #	341672
Year	2017
Model	Volvo A40G
Location City	Greenville
Location State	NC
General Specifications	
New Hours	5056
Old Hours	5047

Lessee: Trader Construction Co
Contract: 502-7522971-059

Unit: 2017 Volvo A40G

UNIT # 341672
Location: ASC, Greenville NC

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Trader Construction Co
Contract: 502-7522971-059

Unit: 2017 Volvo A40G

UNIT # 341672
Location: ASC, Greenville NC


DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Left Dump Cylinder Lower Mount Bushing Coming Out- Repaired	\$0.00
2. Both Body Side Extensions Bent- Removed	\$0.00
3. Left Rear Rear, Right Rear Rear, Right Rear Front Tire Sidewall Cuts- Not Repaired	\$0.00
4. Clean Machine- Done	\$0.00
5. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
6. Dealer to Verify Tire Cuts are Cosmetic Only- Verified	\$0.00
Total	\$0.00

Lessee: Trader Construction Co
Contract: 502-7522971-059

Unit: 2017 Volvo A40G

UNIT # 341672
Location: ASC, Greenville NC



Lessee: Trader Construction Co
Contract: 502-7522971-059

Unit: 2017 Volvo A40G

UNIT # 341672
Location: ASC, Greenville NC



Lessee: Trader Construction Co
Contract: 502-7522971-059

Unit: 2017 Volvo A40G

UNIT # 341672
Location: ASC, Greenville NC