

# 2017 Volvo A40G

Serial #: 341669

Atlantic Waste Landfill  
Waverly, VA  
301-395-0291

- Rear vision system
- Air ride seat
- Air conditioning
- Rotating beacon
- Body exhaust heating kit
- Engine jake brake
- SMU/Hours: 1891
- Overall: Fair
- Radio
- Differential locks
- Computer display
- Mudflaps
- Tailgate
- Start Run: Yes
- Insp Date: 6/5/2019



## General Appearance

<b>Radiator Grille:</b> Good <b>Radiator Shroud:</b> Good <b>Engine Enclosure:</b> Good <b>Hood:</b> Good <b>Stack:</b> Good <b>Right front fender:</b> Good <b>Left front fender:</b> Good <b>Rear frame:</b> Good <b>Front frame:</b> Good	<b>Precleaner bowl:</b> Good <b>Fuel Tank:</b> Good <b>Cab Doors:</b> Good <b>Bumper:</b> Good <b>Cab:</b> Good <b>Steps:</b> Good <b>Grab Irons/Handrails:</b> Good <b>Paint:</b> Good <b>Oil Sample Taken:</b> No
<b>LEGEND OF CONDITIONS:</b> Excellent - New condition. No Repairs Necessary.      Poor - Obvious wear and/or damage. Repairs necessary. Good - No apparent wear or damage, Functions/Operates correctly. No Repairs Necessary.      Not Applicable - Does not apply to this unit Fair - Wear and/or damage apparent. Functions, but not correctly. Repairs recommended.	
<b>NOTES:</b> .	

## Interior Section

<b>Glass:</b> Good <b>Mirrors:</b> Good <b>Seat Belt:</b> Good <b>Back Up Alarm:</b> Good <b>Fan Guards:</b> Good	<b>Neutral Start Switch:</b> Good <b>Fire Suppression System:</b> Not Available <b>Horn:</b> Good
<b>NOTES:</b>	
<b>Dash Console:</b> Good <b>Meter:</b> Good <b>Gauges:</b> Good <b>Control Pattern Decals:</b> Good <b>Switches:</b> Good <b>Windshield Wipers:</b> Good <b>Heater:</b> Good <b>A/C:</b> Good <b>Interior Lights:</b> Good	<b>Seat Cushion:</b> Good <b>Arm Rests:</b> Good <b>Floor Boards/Mats:</b> Good <b>EMS Panel:</b> Good <b>Warnings:</b> Good <b>Door Latches:</b> Good <b>Current Parts Manual:</b> Not Applicable <b>Current Safety Manual:</b> Not Applicable <b>Current O&amp;M Manual:</b> Not Applicable
<b>NOTES:</b>	

## Power Systems

<b>Engine Make Model:</b> Volvo D16J <b>Engine S/N:</b> 101094 <b>Engine Hours:</b> 1891 <b>Oil Leaks:</b> No <b>Blow-by:</b> No <b>Knocking:</b> No <b>Compression in Radiator:</b> No <b>Water in Oil:</b> No <b>Fluid Level OK?:</b> Yes <b>Anit-Freeze Color:</b> Yellow	<b>Oil Pressure:</b> Normal <b>Smoke:</b> No <b>Smoke Color:</b> Not Applicable <b>TurboCharger:</b> Good <b>Fuel Injection System:</b> Good <b>Governor:</b> Good <b>Engine Supports:</b> Good <b>Air Cleaners:</b> Good
<b>NOTES:</b>	
<b>Radiator:</b> Good <b>Coolers:</b> Good <b>Hoses:</b> Good <b>Water Pump:</b> Good	<b>Fan:</b> Good <b>Fan Drive:</b> Good <b>Belts:</b> Good <b>Pulleys:</b> Good
<b>NOTES:</b>	
<b>Batteries:</b> Good <b>Battery Cables:</b> Good <b>Starter:</b> Good <b>Alternator:</b> Good	<b>Wiring:</b> Good <b>Pre-Heater:</b> Good <b>Lighting:</b> Good
<b>NOTES:</b>	

## Power Systems - Continued

<b>Transmission Serial #:</b> - <b>Transmission Type:</b> Auto <b>Transmission Speeds:</b> 9 <b>Transmission Forward:</b> Good <b>Transmission Reverse:</b> Good <b>Case:</b> Good <b>Controls:</b> Good	<b>Seals:</b> Good <b>Torque Converter:</b> Good <b>Temp/Pressure Gauges:</b> Good <b>Transmission Fluid:</b> Good <b>Is the Transmission Noisy?:</b> No <b>Transmission Retarder:</b> Yes
<b>NOTES:</b>	
<b>Steering Linkage:</b> Good <b>Steering Valve:</b> Good <b>Steering Pump:</b> Good <b>Articulation P &amp; B:</b> Good	<b>Left steering cylinder:</b> Good <b>Right steering cylinder:</b> Good <b>Steering joints:</b> Good
<b>NOTES:</b>	
<b>Mechanism:</b> Wet <b>Type:</b> Pedal <b>Performance:</b> Good <b>Brake drums:</b> Good <b>Rotors:</b> Good <b>Control Valve:</b> Good	<b>Lines:</b> Good <b>Compressor:</b> Good <b>Brake linkage:</b> Good <b>Master cylinder:</b> Good <b>Parking brake:</b> Good
<b>NOTES:</b>	
<b>Front axle:</b> Good <b>Front differential:</b> Good <b>Rear axles:</b> Good <b>Rear differentials:</b> Good <b>Front wheel lugs &amp; rims:</b> Good <b>Rear wheel lugs &amp; rims:</b> Good <b>Front axle bolts:</b> Good <b>Rear axle bolts:</b> Good <b>Front axle housing:</b> Good	<b>Rear axle housing:</b> Good <b>U-Joints:</b> Good <b>Front suspension:</b> Good <b>Rear suspension:</b> Good <b>Front a-stay:</b> Good <b>Rear a-stay:</b> Good
<b>NOTES:</b>	

2017 Volvo A40G

(Continued)

Serial #: 341669

## Hydraulics

<b>Right dump cylinder:</b>	Good	<b>Valves:</b>	Good
<b>Left dump cylinder:</b>	Good	<b>Control linkage:</b>	Good
<b>Hose lines:</b>	Poor	<b>Reservoir:</b>	Good
<b>Pumps:</b>	Good	<b>Dump cycle test:</b>	Poor
<b>NOTES:</b>			

2017 Volvo A40G

(Continued)

Serial #: 341669

## Dump Body

<b>Body type:</b>	Bulk	<b>Body pins and bushings:</b>	Good
<b>Body bottom:</b>	Good	<b>Body liner:</b>	Not Available
<b>Body sides:</b>	Good	<b>Tail gate adapter:</b>	Good
<b>Rubber pads:</b>	Good	<b>Tail gate:</b>	Good
<b>Body mounts:</b>	Good	<b>Front spill guard:</b>	Good
<b>NOTES:</b>			

2017 Volvo A40G

(Continued)

Serial #: 341669

## Tires

<b>Front Tire Size:</b>	<b>Left:</b> 29.5R25 70%	<b>Right:</b> 29.5R25 - 67%	<b>Rear Tire Size 1:</b>	<b>Left:</b> 29.5R25 56%	<b>Right:</b> 29.5R25 - 78%
<b>Front Tire Brand:</b>	<b>Left:</b> Bridgestone	<b>Right:</b> Bridgestone	<b>Rear Tire Brand 1:</b>	<b>Left:</b> Bridgestone	<b>Right:</b> Bridgestone
<b>Front Tire Radial or Bias:</b>	<b>Left:</b> Radial	<b>Right:</b> Radial	<b>Rear Tire Radial or Bias:</b>	<b>Left:</b> Radial	<b>Right:</b> Radial
<b>Front Tire Measurement:</b>	<b>Left:</b> 39/32	<b>Right:</b> 37/32	<b>Rear Tire Measurement 1:</b>	<b>Left:</b> 31/32	<b>Right:</b> 43/32
			<b>Rear Tire Size 2:</b>	<b>Left:</b> 29.5R25 69%	<b>Right:</b> 29.5R25 - 65%
			<b>Rear Tire Brand 2:</b>	<b>Left:</b> Bridgestone	<b>Right:</b> Bridgestone
			<b>Rear Tire Radial or Bias:</b>	<b>Left:</b> Radial	<b>Right:</b> Radial
			<b>Rear Tire Measurement 2:</b>	<b>Left:</b> 38/32	<b>Right:</b> 36/32
<b>NOTES:</b> Tread Depth Wear Based On 55/32nds New					



2017 Volvo A40G

(Continued)

Serial #: 341669

## Comments

<b>Public Comments:</b>
-------------------------

2017 Volvo A40G

(Continued)

Serial #: 341669

## Reconditioning

ITEM	QTY	PRICE
1. + Hydraulic Hoses Above Left Steer Cylinder Leaking		\$0.00
2. + All Tires Sidewalls Cut		\$0.00
3. + Clean Machine		\$0.00
4. + Coolers/Radiator Dirty		\$0.00
<b>Total</b>		<b>\$0.00</b>

2017 Volvo A40G

(Continued)

Serial #: 341669



2017 Volvo A40G

(Continued)

Serial #: 341669



2017 Volvo A40G

(Continued)

Serial #: 341669



2017 Volvo A40G

(Continued)

Serial #: 341669



2017 Volvo A40G

(Continued)

Serial #: 341669

