

Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H

UNIT # 622988
Location: ASC Construction
Equipment, Buford GA



VIN	622988
LeaseInspector ID #	622988
Year	2018
Model	Volvo L70H
Location City	Buford
Location State	GA
General Specifications	
New Hours	1283
Old Hours	1281

Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H

UNIT # 622988
Location: ASC Construction
Equipment, Buford GA

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H


UNIT # 622988
Location: ASC Construction
Equipment, Buford GA

ITEM	QTY PRICE
1. Both Front Top Corner Broken Off- Replaced	\$0.00
2. Both Rear Fender Steps Damaged- Replaced	\$0.00
3. Right Side Steps Damaged- Replaced	\$0.00
4. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
5. Dealer to Verify Tire Cuts are Cosmetic Only- Verified	\$0.00
6. Dealer to Determine if Service is Due- Not Due	\$0.00
7. Air Cleaner Dirty- Replaced	\$0.00
8. Right Fornt Tire Sidewall Cut- Verified	\$0.00
9. Blower Switch Knob Missing- Replaced	\$0.00
10. Right Front Fender Damaged- Replaced	\$0.00
11. Left Front Fender Damaged- Replaced	\$0.00
12. Right Rear Fender Damaged- Replaced	\$0.00
13. Left Rear Fender Damaged- Replaced	\$0.00
Total	\$0.00

Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H

UNIT # 622988
Location: ASC Construction
Equipment, Buford GA



Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H


UNIT # 622988
Location: ASC Construction
Equipment, Buford GA



Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H

UNIT # 622988
Location: ASC Construction
Equipment, Buford GA



Lessee: Argos USA
Contract: 502-7694383-036

Unit: 2018 Volvo L70H

UNIT # 622988
Location: ASC Construction
Equipment, Buford GA