VOLVO - INSPECTION REPORT

Volvo, EC380E - Track Excavators

Country: US Date: 01/09/2020 Make: Volvo Serial number: 310937	Dealer: Hoffman Equipment Inspector: Model: EC380E Engine S/N:	Location: Deptford Year: 2017 Hours: 3133 Matris hours:	
Comment:			
Equipped Configuration			
 [X] Yes EROPS [X] Yes Air conditioning [] Yes Stick short [X] Yes Stick medium [] Yes 2 Piece boom [] Yes Long reach arrangement [] Yes Drill arrangement [] Yes Recycling arrangement [] Yes Demolition arrangement [] Yes Mass excavator arrangement [] Yes Forestry arrangement 	 Yes Cab risers Yes Cab riser hydraulic Yes Standard car body Yes Hydraulic retractable UC Yes Auxiliary hydraulics Yes Hose rupture valves Yes Boom float Yes Attachment circuits Yes Leveling blade Yes Cushion boom cylinder 	 Yes Proportional joystick controls Yes Joystick controls Yes Thumb - Manual Yes Thumb hydraulic Yes Counterweight removal sys. Yes Long undercarriage Yes Quick coupler manual Yes Quick coupler hydraulic Yes Auto Lube Yes Travel pedal 	

Comment:

Images

Comment:

Operators Station

Seat and armrest	[X] Good
Dash and console	[X] Good
Floor Board/Mat	[X] Good
Cab glass	[X] Good
Mirrors	[X] Good
Interior light	[X] Good
Switches	[X] Good
Wipers	[X] Good
Gauges	[X] Good
Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
Operators station condition summary	
Comment:	

Outside appearance

Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Car body	[X] Good
Fenders	[X] Good
OEM Welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance	
condition summary	

Comment:

Safety condition

Safety decals in place	[X]Yes
Operators manual	[X]Yes
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good
Brake hold	[X] Good
ROPS Structure	[X] Good
Guarding	[X] Good
CAB	[X] Good
Safety condition summary	
-	
Comment:	

Electrical condition

Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches	[X] Good

Lighting	[X] Good
Engine preheater	[X] Good
Batteries / Connections	[X] Good
Battery disconnect	[X] Good
switch Electrical condition [summary	
Comment:	

Engine condition

Oil level OK	[X]Yes
Water in oil	[X] No
Compression	[X] No
Blow by	[X] No
Engine knocking	[X] No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	[X] Good
Muffler	[X] Good
Fuel injection system	[X] Good
Head gasket	[X] Good
Head	[X] Good
Fan guard	[X] Good
Belts & pulleys	[X] Good
Wiring harness	[X] Good
Starter	[X] Good
Alternator	[X] Good
Seals & gaskets	[X] Good
Engine mounts	[X] Good
Brackets	[X] Good
AC Compressor	[X] Good
Air filters	[X] Good
Engine condition summary	
Saminary	

Comment:

Cooling system

Coolant color	Yellow
Radiator	[X] Good
Water pump	[X] Good
Oil cooler	[X] Good
Fan	[X] Good
Fan drive	[] Good [] Fair [] Poor Remarks:
Hoses	[X] Good
Cooling system summary	
Comment:	

Hydraulics condition

Boom cylinders	[X] Good
Stick cylinders	[X] Good
Bucket cylinders	[X] Good
Blade cylinders	[] Good [] Fair [] Poor Remarks:
Thumb cylinders	[] Good [] Fair [] Poor Remarks:
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Swing bearing	[X] Good
Swing gear	[X] Good
Swing motor	[X] Good
Hydraulic swivel	[X] Good
Travel motors	[X] Good
Pump drive	[X] Good
Planetaries left	[X] Good
Planetaries right	[X] Good
Controls	[X] Good
Overall condition Summary	[X] Good
Comment:	

Boom & arm condition

Lower stick pins	[X] Good
Upper stick pins	[X] Good
Stick condition	[X] Good

Stick length	3.9
Boom length	6.45
Lower boom pins	[X] Good
Upper boom pins	[X] Good
Boom condition	[X] Good
Summary	
Comment:	
Comment:	

Bucket & other attachments

Bucket type / Size	65"
Coupler type	No Coupler
Bucket serial	
Coupler serial	No Coupler
Bucket W / Teeth	[X]Yes
Addtl attachments	
Bolt on smooth	[X] No
Bolt on edge	[] Good [] Fair [] Poor Remarks:
Bucket mounts	[X] Good
Bucket teeth / Segments	[X] Good
Bucket sides	[X] Good
Bucket floor	[X] Good
Bucket bottom	[X] Good
Coupler	[] Good [] Fair [] Poor Remarks:
Boom / Frame	[X] Good
Boom / Bucket pins & bushings	[X] Good
Summary	
Comment:	


Undercarriage condition

Roller frame right	[X] Good
Roller frame left	[X] Good
Track adjusters	[X] Good

Overall condition	[X] Good
Links left	125
Links left	60%
Internal pin wear left	867
Internal pin wear left	85%
External pin wear left	70
External pin wear left	70%
Trackshoe/ Grouser left	32
Trackshoe/ Grouser left	70%
Front Idler left	23
Front Idler left	90%
Sprockets left	2
Sprockets left	70%
Front Carrier Rollers left	167
Front Carrier Rollers left	95%
Center Carrier Rollers left	
Center Carrier Rollers left	
Rear Carrier Rollers left	167
Rear Carrier Rollers left	95%
Links right	125
Links right	60%
Internal pin wear right	866
Internal pin wear right	90%
External pin wear right	70
External pin wear right	70%
Trackshoe/ Grouser right	32
Trackshoe/ Grouser right	30%
Front Idler right	23
Front Idler right	90%
Sprockets right	2

Sprockets right	70%
Front Carrier Rollers right	167
Front Carrier Rollers right	95%
Center Carrier Rollers right	
Center Carrier Rollers right	
Rear Carrier Rollers right	167
Rear Carrier Rollers right	95%
Bottom rollers S or D	S
Undercarriage brand	Volvo
Link part number	
Pins & bushings turned	No
Comment:	

Bottom rollers S or D



General Comments

Legend (5 star rating)	[]5 []4 []3 []2 []1
Paint general	[] Good [] Fair [] Poor Remarks:
Comment:	