

Equipment Inspection Form

Type: Compactor

19870140

7606

Please provide the following information for your equipment.

General Information

Customer Full Name: []	Equipment Name: []	Location Description: []	Current Postal Code: []
Country: []	Equipment Application: []	Serial Number: 289006	IC Number: []
Equipment Category: []	Make: []	Model: DD140	Year: []
Matris Hours: []	Inspector Name: Cosy	Operating Hours: 1265	Requested Price (in USD): []

Comments:

Center hose/wiring clamp broken/missing

Features

EROPS: <input type="radio"/> Yes <input checked="" type="radio"/> No	Air Conditioning: <input type="radio"/> Yes <input checked="" type="radio"/> No	ROPS: <input checked="" type="radio"/> Yes <input type="radio"/> No	Heat: <input type="radio"/> Yes <input checked="" type="radio"/> No	Scraper: <input checked="" type="radio"/> Yes <input type="radio"/> No	Hydraulic Options - Auxiliary? <input type="radio"/> Yes <input checked="" type="radio"/> No
Quick Coupler: []	Other Options: <input type="radio"/> Yes <input checked="" type="radio"/> No Other Options comments: []	Attachments: <input type="radio"/> Yes <input checked="" type="radio"/> No Attachments comments: []			
Windshield: <input type="radio"/> Yes <input checked="" type="radio"/> No	Features Appearance: <input type="radio"/> 5 - Excellent <input checked="" type="radio"/> 4 <input type="radio"/> 3 <input type="radio"/> 2 <input type="radio"/> 1 - Poor	Summary: []			

Appearance

Body Condition: <input type="radio"/> N/A <input type="radio"/> Good <input checked="" type="radio"/> Fair <input type="radio"/> Repair Comments: []	Paint: <input type="radio"/> Good <input checked="" type="radio"/> Fair <input type="radio"/> Repair Comments: asphalt stained	Decals: <input type="radio"/> N/A <input type="radio"/> Good <input checked="" type="radio"/> Fair <input type="radio"/> Repair Comments: []	
Lights/ Mirrors: <input type="radio"/> N/A <input checked="" type="radio"/> Good <input checked="" type="radio"/> Fair <input type="radio"/> Repair Comments: 3 dont work	Latches: <input type="radio"/> N/A <input checked="" type="radio"/> Good <input type="radio"/> Fair <input type="radio"/> Repair Comments: []	Fluid Fill Caps: <input checked="" type="radio"/> Good <input type="radio"/> Fair <input type="radio"/> Repair Comments: []	
Water Tanks: <input checked="" type="radio"/> Good <input type="radio"/> Fair <input type="radio"/> Repair Comments: []	Seats: <input checked="" type="radio"/> Good <input type="radio"/> Fair <input type="radio"/> Repair Comments: []	Overall Appearance: <input type="radio"/> 5 - Excellent <input checked="" type="radio"/> 4 <input type="radio"/> 3 <input type="radio"/> 2 <input type="radio"/> 1 - Poor	Summary: []

Run Test

Hours: Good Fair Repair

Comments:

Battery/ Starting: Good Fair Repair

Comments:

Gauges: Good Fair Repair

Comments:

Water System: Good Fair Repair

Comments:

Controls: Good Fair Repair

Comments:

Switches: Good Fair Repair

Comments:

Console Swivel: Good Fair Repair

Comments:

a little loose

Swivel/ Articulated Joint: Good Fair Repair

Comments:

Overall Run Test:

- 5 - Excellent
- 4
- 3
- 2
- 1 - Poor

Summary:

Safety

Safety Decals: N/A Good Repair

Comments:

Seatbelts: N/A Good Repair

Comments:

Rails: Good Fair Repair

Comments:

Park Brake: Good Fair Repair

Comments:

Locking Bar: N/A Good Repair

Comments:

Operators Manual/ Handbook: N/A Good Repair

Comments:

none

ROPS Damage: N/A Good Fair Repair

Comments:

none

Back-up Alarm: N/A Good Fair Repair

Comments:

Horn: N/A Good Fair Repair

Comments:

Overall Safety:

- 5 - Excellent
- 4
- 3
- 2
- 1 - Poor

Summary:

Hydraulics Condition

Hydraulics: Good Fair Repair

Comments:

Cylinders: Good Fair Repair

Comments:

Hose/ Lines: Good Fair Repair

Comments:

Pumps/ Valves: Good Fair Repair

Comments:

Isolators: Good Fair Repair

Comments:

Hydraulic Blocks: Good Fair Repair

Comments:

Steering: Good Fair Repair

Comments:

Drum Seats: Good Fair Repair

Comments:

Oil Cooler: Good Fair Repair

Comments:

Drive Motor Type:

Overall Hydraulics:

- 5 - Excellent
- 4
- 3
- 2
- 1 - Poor

Summary:

leak around pump area

Engine Condition

Engine Oil Level:

Good Fair Repair

Comments:

[Empty comment box]

Visible Leaks:

Good Fair Repair

Comments:

none

Filters:

Good Fair Repair

Comments:

check for service

Blow-By:

Yes No

Last Serviced Hours:

Last Serviced Date:

[Empty date box]

Belts:

Good Fair Repair

Comments:

[Empty comment box]

Linkage:

Good Fair Repair

Comments:

[Empty comment box]

Exhaust Cap:

Good Fair Repair

Comments:

[Empty comment box]

Wiring/ Harness:

Good Fair Repair

Comments:

Center of machine to engine

Fuses:

Good Fair Repair

Comments:

[Empty comment box]

Fan Shroud:

Good Fair Repair

Comments:

[Empty comment box]

Radiator Condition:

Good Fair Repair

Comments:

[Empty comment box]

Hose/ Lines:

Good Fair Repair

Comments:

[Empty comment box]

Antifreeze:

< 32F > 32F Replace

Comments:

[Empty comment box]

Engine Shut Down:

Good Fair Repair

Comments:

[Empty comment box]

Engine Smoke Color:

Normal Black Blue White

Comments:

[Empty comment box]

Overall Engine Condition:

5 - Excellent
 4
 3
 2
 1 - Poor

Summary:

[Empty summary box]

Overall Condition

Overall Condition:

5 - Excellent
 4
 3
 2
 1 - Poor

Summary:

[Empty summary box]