VOLVO - INSPECTION REPORT

Volvo, A45g - Articulated haul trucks

Images















Cor		

Country: US Date: 08/01/2019 Make: Volvo Serial number: 342056

Trans S/N: 1700107681

Dealer: Arnold Machinery Company

Inspector: Mike seifert Model: A45g Engine S/N: 102231

Location: Las vgas Year: 2017 Hours: 4764 Matris hours: 4763

Comment:

Equipped Configuration

[X] Yes Standard Cab] Yes Water Tank] Yes LED Light [X] Yes Strobe Light [] Yes Hydraulic switch control [X] Yes Hydraulic lever control] Yes Auto Lube System] Yes Fire Suppression System [X] Yes Mud Flaps

Comment:

Operators Station

Seats and armrest [X] Good

Dash and console [X] Good

Floor Board/Mat [X] Good

Cab glass [X] Good

Mirrors [X] Good

Interior light [X] Good

Switches [X] Good

Wipers [X]Good

Gauges [X] Good

Hydraulic controls	[X] Good
Powertrain controls	[X] Good
AC cooling	[X] Good
CAB Interior	[X] Good
Operators station condition summary	
Comment:	
Outside appearance	ee
Steps	[X] Good
Hand rails	[X] Good
Counterweight /	[X] Good
Bumper	
Grill	[X] Good
Hood	[X] Good
Exhaust stack	[X] Good
Pre-cleaner bowl	[X] Good
Front fenders	[X] Good
Hyd tank	[X] Good
Fuel tank	[X] Good
Def tank	[X] Good
Front frame & welds	[X] Good
Rear frame & welds	[X] Good
Sheet metal	[X] Good
Paint	[X] Good
Outside appearance condition summary	
Comment:	
Safety condition	
Safety decals in place	[X]Yes
Operators manual	[X]Yes
Safety handles	[X] Good
Seat belt	[X] Good
Horn	[X] Good
Back up alarm	[X] Good
Brake lights	[X] Good
Turn signals	[X] Good

Hazard lights

[X] Good

ROPS Structure	[X] Good
CAB	[X] Good
Safety condition summary	
Comment:	
Elastada el comunidad	
Electrical condition	n
Computer	[X] Good
ECM'S	[X] Good
Monitor / Display	[X] Good
Wiring harness's	[X] Good
Key switch	[X] Good
Switches Lighting	[X] Good [X] Good
Engine preheater	[X] Good
Batteries / Connections	
Battery disconnect	[X] Good
switch	
Electrical condition summary	
Comment:	
Engine condition	
Oil level OK	[X]Yes
Water in oil	[X] No
Compression in radiator	[X] No
Blow by	[X]No
Engine knocking	[X] No
CE PLATE	[X]Yes
Oil pressure	[X] Good
Oil leaks	[X] No
EPA DECAL	[X]Yes
Turbo charger	[X] Good
Exhaust manifold	
	[X] Good
Muffler	[X] Good
Muffler Fuel injection system	

[X] Good

Head

Fan guard	[X] Good	
Belts & pulleys	[X] Good	
Wiring harness	[X] Good	
Starter	[X] Good	
Alternator	[X] Good	
Seals & gaskets	[X] Good	
Engine mounts	[X] Good	
Brackets	[X] Good	
AC Compressor	[X] Good	
Air filters	[X] Good	
Engine condition summary		
Comment:		
Cooling system		
Coolant color	Red	
Radiator	[X] Good	
Water pump	[X] Good	
Oil cooler	[X] Good	
Fan	[X] Good	
Fan drive	[X] Good	
Hoses	[X] Good	
Cooling system summary		
Comment:		7
Confinent.		J
Transmission co	ndition	
Oil level OK	[X]Yes	
Water in oil	[X] No	
Any leaks	[X]No	
Torque converter	[X] Good	
Case	[X] Good	
Pump	[X] Good	
Hoses	[X] Good	
Retarder	[X] Good	
Transfer case	[X] Good	

Shifting forward	[X] Good
Shifting reverse	[X] Good
Transmission summary	
Comment:	
Axels-Final Drives-	Brakes
Front differential	[X] Good
Center differential	[X] Good
Rear differential	[X] Good
Differential supports	[X] Good
Drive shafts	[X] Good
UV Joints	[X] Good
Planetaires front	[X] Good
Planetaires center	[X] Good
Planetaires rear	[X] Good
Hoses / Lines	[X] Good
Torsion rods	[X] Good
Holds in park	[X]Yes
Brakes wet	[X]Yes
Holds thru all gears	[X]Yes
Brakes dry	[X] No
Brake disk / calipers	[X] Good
Brake lines	[X] Good
Seals	[X] Good
Parking brake	[X] Good
Summary	
Comment:	
Steering & articular	tion condition
Steering cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good
Lines / Hoses	[X] Good
Secondary steering	[X] Good
Steering pins &	[X] Good
bushings	

Steering wheel tilt & function	[X] Good
Articulation pins &	[X] Good
bushings	[^] Good
Summary	
•	
Comment:	
Hydraulics condition	on
Bed lift cylinders	[X] Good
Pumps	[X] Good
Valves	[X] Good
Hoses	[X] Good
Fittings	[X] Good
Tank	[X] Good
Controls	[X] Good
Bed float	[X] Good
Operational condition	[X] Good
Summary	
Comment:	
Comment.	
Bed & other attach	nments
Bed type / Size	
200 1,00 / 0.20	
Tailgate S / N	
Bed serial	
Addtl attachments	
Spill guard	[X] Good
Body	[X] Good
Bed liner	[X] Good
Bed sides	[X] Good
Bed floor	[X] Good
Wear plates	[X] Good
Tailgate	[X] Good
Pins & bushings	[X] Fair Remarks: Slightly worn still operable
Summary	
Comment:	
Tires & rims	
Make	Michelin
Serial	Fpv2537a3a. 35/32
% Remaining	

Make	Michelin
Serial	Vpv4756a4a. 40/32
% Remaining	
Make	Michelin
Serial	Fpv2540a0a. 40/32
% Remaining	
Make	Michelin
Serial	Fpv2533a7a. 40/32
% Remaining	
Make	Michelin
Serial	Fpv2602a8a. 40/32
% Remaining	
Make	Michelin
Serial	Fpv2536a4a. 36/32
% Remaining	
Recapped	[X] No
Tread cuts	[X] Yes Remarks: Small
Side wall cuts	[X] Yes Remarks: Small
Tire size the same	[X] Yes Remarks: 29.5r25
Overall tire condition	[X] Good
Rims	[X] Good
Lug nuts & studs	[X] Good
Comment:	
General Comment	s
Legend (5 star rating) Paint general	[]5 []4 []3 []2 []1 []Good []Fair []Poor Remarks:
Comment:	