

Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G

UNIT # 341661
Location: ASC, Greenville NC



SPECIFICATIONS

VIN	341661
LeaseInspector ID #	341661
Year	2017
Model	Volvo A40G
Location City	Greenville
Location State	NC
General Specifications	
New Hours	5215
Old Hours	5214

Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G

UNIT # 341661
Location: ASC, Greenville NC

**ADDITIONAL FEATURES OF THIS
VEHICLE
COMMENTS**

Appraiser Comments:

Creditor Comments:

Public Comments:

Starts/Runs: Yes

Overall: Fair

Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G

UNIT # 341661
Location: ASC, Greenville NC



DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Go To Service Mode Warning On- VERIFIED no active errors	\$0.00
2. Dump Body Top Extender Bent- Removed	\$0.00
3. Body Pins and Bushings Have Excessive Play- Not ReplacedPin and bushing wear has been checked and i-	\$0.00
4. All 4 Rear Tire Sidewall Cut- Not Replaced-Replaced Cosmetic cuts only. No leaks	\$0.00
5. 1 Step Bent- Not Replaced-No issues with steps found	\$0.00
6. Clean Machine- Done	\$0.00
7. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
8. Dealer to Determine if Service is Due- Not Done-No service due	\$0.00
9. Dealer to Verify Itre Cuts are Cosmetic Only- Verified	\$0.00
Total	\$0.00

Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G


UNIT # 341661
Location: ASC, Greenville NC



Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G

UNIT # 341661
Location: ASC, Greenville NC



Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G

UNIT # 341661
Location: ASC, Greenville NC



Lessee: Trader Construction Co
Contract: 502-7522971-057

Unit: 2017 Volvo A40G

UNIT # 341661
Location: ASC, Greenville NC