

Lessee: Ripa & Associates
Contract: 502-5040598-014

Unit: 2016 Volvo A40G

UNIT # 1216
Location: Flagler Construction
Equipment, Tampa FL



SPECIFICATIONS

VIN	1216
LeaseInspector ID #	1216
Year	2016
Model	Volvo A40G
Location City	Tampa
Location State	FL
General Specifications	
New Hours	4534
Old Hours	4533

Lessee: Ripa & Associates
Contract: 502-5040598-014

Unit: 2016 Volvo A40G

UNIT # 1216
Location: Flagler Construction
Equipment, Tampa FL

ADDITIONAL FEATURES OF THIS VEHICLE
COMMENTS

Appraiser Comments:

Creditor Comments:

Updated Per VFS

Public Comments:

Updated Per VFS

Starts/Runs: Yes

Overall: Fair

Lessee: Ripa & Associates
Contract: 502-5040598-014

Unit: 2016 Volvo A40G

UNIT # 1216
Location: Flagler Construction
Equipment, Tampa FL

DEFICIENCY REVIEW

ITEM	QTY PRICE
1. Clean Machine- Done	\$0.00
2. Clean Machine Inside, Out, Engine, Undercarriage- Done	\$0.00
3. Dealer to Determine if Service is Due- Up to Date	\$0.00
4. Dealer to Verify Tire Cuts are Cosmetic Only- Verified	\$0.00
5. Coolant Level Low- Repaired	\$0.00
6. Engine Oil Seep Injector Harness Plug- Repaired	\$0.00
7. Engine Oil Seep Left side of Engine- Repaired	\$0.00
8. Collection Bottom of Drop Box- Repaired	\$0.00
9. Wet Brake Fluid Level Low- Repaired	\$0.00
10. Left Front Tire Cut-	\$0.00
11. Left Rear Tire Cut-	\$0.00
12. Left Middle Tire Cut-	\$0.00
13. Cigarette Lighter Missing- Replaced	\$0.00
Total	\$0.00

Lessee: Ripa & Associates
Contract: 502-5040598-014

Unit: 2016 Volvo A40G

UNIT # 1216
Location: Flagler Construction
Equipment, Tampa FL



**Lessee: Ripa & Associates
Contract: 502-5040598-014**

Unit: 2016 Volvo A40G

**UNIT # 1216
Location: Flagler Construction
Equipment, Tampa FL**

